

AD-A087 792

GAI CONSULTANTS INC. MONROEVILLE PA F/G 13/13
NATIONAL DAM INSPECTION PROGRAM, ROSE VALLEY LAKE DAM (NDI I.D.--ETC(U)
JUL 80 B M MIHALCIN DACW31-80-C-0016

UNCLASSIFIED

1 OF 1
AD-A
000 000

ML

END
DATE
FILMED
80
DTIC

LEVEL II

①

B.S.


**SUSQUEHANNA RIVER BASIN
MILL CREEK, LYCOMING COUNTY**

**PENNSYLVANIA
ROSE VALLEY LAKE DAM**

**NDI I.D. No. PA-01127
PENNDER I.D. No. 41-97**

THIS DOCUMENT IS BEST QUALITY PRACTICE
THE COPY FURNISHED TO DDC CONTAINED A
SIGNIFICANT NUMBER OF PAGES WHICH DO NOT

**PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM**



PREPARED FOR

**DEPARTMENT OF THE ARMY
Baltimore District, Corps of Engineers
Baltimore, Maryland 21203**

Ber

PREPARED BY

**GAI CONSULTANTS, INC.
570 BEATTY ROAD
MONROEVILLE, PENNSYLVANIA 15146**

JULY 1980

**DTIC
ELECTE
AUG 1 2 1980**

*This document has been approved
for public release and sale; its
distribution is unlimited.*

GAI CONSULTANTS, INC.
-DACW31-80-C-0016

80 3 11 137

ADA 087792

ORIGINAL CONTAINS COLOR PLATES: ALL DDC
REPRODUCTIONS WILL BE IN BLACK AND WHITE.

DDC FILE COPY

DISCLAIMER NOTICE

**THIS DOCUMENT IS BEST QUALITY
PRACTICABLE. THE COPY FURNISHED
TO DTIC CONTAINED A SIGNIFICANT
NUMBER OF PAGES WHICH DO NOT
REPRODUCE LEGIBLY.**

1

PREFACE

This report is prepared under guidance contained in the Recommended Guidelines for Safety Inspection of Dams, for Phase I investigations. Copies of these guidelines may be obtained from the Office of Chief of Engineers, Washington, D. C. 20314. The purpose of a Phase I investigation is to identify expeditiously those dams which may pose hazards to human life or property. The assessment of the general condition of the dam is based upon available data and visual inspections. Detailed investigation and analyses involving topographic mapping, subsurface investigations, testing, and detailed computational evaluations are beyond the scope of a Phase I investigation; however, the investigation is intended to identify any need for such studies.

In reviewing this report, it should be realized that the reported condition of the dam is based on observations of field conditions at the time of inspection along with data available to the inspection team.

It is important to note that the condition of a dam depends on numerous and constantly changing internal and external conditions, and is evolutionary in nature. It would be incorrect to assume that the present condition of the dam will continue to represent the condition of the dam at some point in the future. Only through frequent inspections can unsafe conditions be detected and only through continued care and maintenance can these conditions be prevented or corrected.

Phase I inspections are not intended to provide detailed hydrologic and hydraulic analyses. In accordance with the established guidelines, the spillway design flood is based on the estimated "Probable Maximum Flood" for the region (greatest reasonably possible storm runoff), or fractions thereof. The spillway design flood provides a measure of relative spillway capacity and serves as an aid in determining the need for more detailed hydrologic and hydraulic studies, considering the size of the dam, its general condition, and the downstream damage potential.

Approved for Release by NSA on 09-10-2013 pursuant to E.O. 13526

National Dam Inspection Program.
Rose Valley Lake Dam (NDI I.D. Number
PA-01127, PennDER I.D. Number 41-97),
Susquehanna River Basin, Mill Creek,
Lycoming County, Pennsylvania.

PHASE I INSPECTION REPORT,
NATIONAL DAM INSPECTION PROGRAM.

ABSTRACT

Rose Valley Lake Dam: (NDI I.D. No. PA-01127

Owner: Pennsylvania Fish Commission
State Located: Pennsylvania (PennDER I.D. No.
41-97)
County Located: Lycoming
Stream: Mill Creek
Inspection Date: 23 April 1980
Inspection Team: GAI Consultants, Inc.
570 Beatty Road
Monroeville, Pennsylvania 15146

The visual inspection, operational history, and hydrologic/
hydraulic analysis indicate that the facility is in excellent
condition.

The size classification of the facility is intermediate and
its hazard classification is considered to be high. In
accordance with the recommended guidelines, the Spillway
Design Flood (SDF) for the facility is the PMF (Probable
Maximum Flood). Results of the hydrologic and hydraulic
analysis indicate the facility is capable of passing and/or
storing the PMF. Consequently, its spillway is considered
adequate.

It is recommended that the owner immediately,

(a.) Provide positive drainage for the area between the
left spillway wingwall and left abutment hillside and

ROSE VALLEY LAKE DAM - NDI No. PA 01127

(b.) Repair and seal all concrete cracks observed along the left spillway wingwall.

GAI Consultants, Inc.

Approved by:

Bernard M. Mihalcin
Bernard M. Mihalcin, P.E.


James W. Peck
JAMES W. PECK
Colonel, Corps of Engineers
District Engineer



Date 11 July 1980

Date 31 July 1980

Accession For	
NTIS GRA&I	<input checked="checked" type="checkbox"/>
DDC TAB	<input type="checkbox"/>
Unannounced	<input type="checkbox"/>
Justification	<i>for 50 on file</i>
By	
Date	
Classification	
Availability Codes	
Available/for	Special
<i>A</i>	<i>Q</i>



OVERVIEW PHOTOGRAPH

TABLE OF CONTENTS

	<u>Page</u>
PREFACE	i
ABSTRACT.	ii
OVERVIEW PHOTOGRAPH	iv
TABLE OF CONTENTS	v
SECTION 1 - GENERAL INFORMATION	1
1.0 Authority	1
1.1 Purpose	1
1.2 Description of Project.	1
1.3 Pertinent Data.	2
SECTION 2 - ENGINEERING DATA.	5
2.1 Design.	5
2.2 Construction Records.	6
2.3 Operational Records	6
2.4 Other Investigations.	6
2.5 Evaluation.	6
SECTION 3 - VISUAL INSPECTION	7
3.1 Observations.	7
3.2 Evaluation.	8
SECTION 4 - OPERATIONAL PROCEDURES.	9
4.1 Normal Operating Procedure.	9
4.2 Maintenance of Dam.	9
4.3 Maintenance of Operating Facilities	9
4.4 Warning System.	9
4.5 Evaluation.	9
SECTION 5 - HYDROLOGIC/HYDRAULIC EVALUATION	10
5.1 Design Data	10
5.2 Experience Data	10
5.3 Visual Observations	10
5.4 Method of Analysis.	10
5.5 Summary of Analysis	10
5.6 Spillway Adequacy	11
SECTION 6 - EVALUATION OF STRUCTURAL INTEGRITY.	12
6.1 Visual Observations	12
6.2 Design and Construction Techniques.	12
6.3 Past Performance.	12
6.4 Seismic Stability	13
SECTION 7 - ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES	14
7.1 Dam Assessment.	14
7.2 Recommendations/Remedial Measures	14

TABLE OF CONTENTS

APPENDIX A - VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES
APPENDIX B - ENGINEERING DATA CHECKLIST
APPENDIX C - PHOTOGRAPHS
APPENDIX D - HYDROLOGY AND HYDRAULICS ANALYSES
APPENDIX E - FIGURES
APPENDIX F - GEOLOGY

PHASE I INSPECTION REPORT
NATIONAL DAM INSPECTION PROGRAM
ROSE VALLEY LAKE DAM
NDI# PA-01127, PENNDR# 41-97

SECTION 1
GENERAL INFORMATION

1.0 Authority.

The Dam Inspection Act, Public Law 92-367, authorized the Secretary of the Army, through the Corps of Engineers to initiate a program of inspection of dams throughout the United States.

1.1 Purpose.

The purpose is to determine if the dam constitutes a hazard to human life or property.

1.2 Description of Project.

a. Dam and Appurtenances. Rose Valley Lake Dam is a zoned earth embankment approximately 26 feet high and 516 feet long, including spillway. The facility is provided with an uncontrolled, rectangular, concrete chute channel spillway and stilling basin located at the left abutment. The spillway crest consists of a trapezoidal shaped weir structure 80 feet in length. The outlet works consists of a 4-foot square reinforced concrete culvert that discharges at the downstream embankment toe. Flow through the culvert is regulated by both a 36-inch diameter slide gate and removable stop logs set within a concrete vertical riser positioned along the upstream embankment face.

b. Location. Rose Valley Lake Dam is located on Mill Creek in Gamble Township, Lycoming County, Pennsylvania. The community of Trout Run, Pennsylvania is situated about three miles southwest of the dam at the intersection of U. S. Route 15 and Pennsylvania Route 14. The dam and reservoir are contained within the Bodines, Pennsylvania 7.5 minute U.S.G.S. topographic quadrangle (see Figure 1, Appendix E). The coordinates of the dam are N41°23.1' and W76°59.9.

c. Size Classification. Intermediate (26 feet high, 6500 acre-feet storage capacity at top of dam).

d. Hazard Classification. High (see Section 3.1.e).

e. Ownership. Pennsylvania Fish Commission
P. O. Box 1673
Harrisburg, Pennsylvania 17120

f. Purpose. Recreation.

g. Historical Data. Rose Valley Lake Dam was designed by the Pennsylvania Fish Commission as a public fishing and recreational facility. The project was completed in 1972. The general contractor responsible for construction was the Giffin Construction Company of LeRaysville, Pennsylvania. No major modifications have been made to the facility since its completion.

1.3 Pertinent Data.

a. Drainage Area (square miles). 3.4

b. Discharge at Dam Site.

Discharge Capacity of Outlet Conduit - Discharge curves are not available.

Discharge Capacity of Spillway at Maximum Pool = 4620 cfs (see Appendix D, Sheet 10).

c. Elevation (feet above mean sea level). The following elevations were obtained from available drawings and through field measurements based on the elevation of the spillway crest at 1235.0 feet (see Appendix D, Sheet 1).

Top of Dam	1241.0
Maximum Design Pool	1240.5
Maximum Pool of Record	Not known.
Normal Pool	1235.0
Spillway Crest	1235.0
Upstream Inlet Invert	1215.5
Downstream Outlet Invert	1215.0
Streambed at Dam Centerline	1215.0
Maximum Tailwater	Not known.

d. Reservoir Length (feet).

Top of Dam	6400
Normal Pool	6200

e. Storage (acre-feet).

Top of Dam	6500
Maximum Design Pool	6260
Normal Pool	3940
Design Surcharge	240

f. Reservoir Surface (acres).

Top of Dam	447
Maximum Design Pool	441
Normal Pool	389

g. Dam.

Type	Zoned earth.
Length	436 feet (excluding spillway).
Height	26 feet (field measured; crest to downstream outlet invert).
Top Width	15 feet (field). 16 feet (design).
Upstream Slope	3H:1V
Downstream Slope	2.5H:1V
Zoning	Embankment constructed with four zones: selected impervious fill; class "A" fill; class "B" fill; selected pervious material. See notes on Figure 5 for description of zone materials.
Impervious Core	Central core comprised of selected impervious material. Carried full height of dam and has 1H:2V side slopes.

Cutoff	12-foot wide trench excavated to rock and backfilled with selected impervious material.
Grout Curtain	None indicated.
h. <u>Diversion Canal and Regulating Tunnels.</u>	None.
i. <u>Spillway.</u>	
Type	Uncontrolled, rectangular, concrete chute channel constructed with a trapezoidal shaped concrete weir.
Crest Elevation	1235.0
Crest Length	80 feet.
j. <u>Outlet Conduit.</u>	
Type	4-foot square reinforced concrete culvert.
Length	138 feet (inlet to outlet).
Closure and Regulating Facilities	Flows through outlet are controlled by both a 36-inch diameter slide gate and removable stop logs set in grooves within a reinforced concrete control tower riser.
Access	Control tower accessible from embankment crest.

SECTION 2 ENGINEERING DATA

2.1 Design.

a. Design Data Availability and Sources. No formal design reports are available. The Pennsylvania Fish Commission maintains an extensive file on this facility that includes design calculations and drawings, boring logs, laboratory and field test results, and contract specifications. In addition, a report entitled, "Geology of the Proposed Mill Creek Dam Site" by William D. Sevon of the Pennsylvania Geological Survey is also available. PennDER files contain miscellaneous correspondence, construction progress reports and photographs.

b. Design Features.

1. Embankment. The embankment is designed as a zoned earth structure consisting of four distinct zones as detailed and defined in Figure 5. Selected impervious fill comprises the core and cutoff trench. The core is apparently carried the full height of the dam and has 1H:2V side slopes. The upstream zone consists of selected semi-impervious material (class "A" fill). Riprap is provided on the 3H:1V upstream slope between the top of dam and elevation 1231.0. The downstream zone consists of selected semi-impervious material (class "B" fill) distinct from the material used in the upstream zone. The embankment outer shell is composed of selected pervious material. The downstream embankment face is sloped at 2.5H:1V. A 2-foot thick filter is shown to have been placed beneath the downstream zone with a toe drain at the downstream toe of the fill.

2. Appurtenant Structures.

a) Spillway. The spillway at Rose Valley Lake Dam is a reinforced concrete chute channel with a trapezoidal shaped overflow weir located at the left abutment. The crest length of the weir measures 80 feet and is flanked by vertical concrete wingwalls that provide 6 feet of freeboard (see Figures 3 and 6).

b) Outlet Works. The outlet works consists of a reinforced concrete riser and 4-foot square horizontal culvert which discharges at the downstream embankment toe. Flows through the conduit are controlled by both a 36-inch diameter slide gate and removable stop logs set in grooves within the control tower riser (see Figures 3 and 10).

c. Specific Design Data and Criteria. The dam and its appurtenances are, for the most part, proven standard Pennsylvania Fish Commission designs. Calculations contained in PFC files indicate that the embankment and spillway design were based on procedures and guidelines contained in the texts "Design of Small Dams" by the U. S. Bureau of Reclamation and "Handbook of Applied Hydraulics" by Davis and Sorensen. The spillway was sized to meet the requirements of the Pennsylvania "C" Curve.

2.2 Constructions Records.

Design drawings, contract specifications, construction progress reports and photographs are available from PennDER and Pennsylvania Fish Commission files. Some soils and concrete field test data are also available.

2.3 Operational Records.

No records of the day-to-day operation of this facility are maintained.

2.4 Other Investigations.

No formal investigations have been performed on this facility subsequent to its construction.

2.5 Evaluation.

The available data indicate the facility was designed and constructed in accordance with modern accepted criteria and techniques. The information available is considered adequate to make a reasonable Phase I assessment of the facility.

SECTION 3 VISUAL INSPECTION

3.1 Observations.

a. General. The general appearance of this project indicates the dam and its appurtenances are currently in excellent condition.

b. Embankment. Observations made during the visual inspection indicate the embankment is in excellent condition. No evidence of sloughing, erosion, seepage through the embankment face, excessive settlement, animal burrows, or signs of maintenance neglect were observed (see Photograph 1). A poor drainage condition was observed between the spillway wingwall and left abutment hillside. Figure 3 indicates that a rock gutter was to have been provided at the base of the abutment cut; however, it was apparently never constructed.

c. Appurtenant Structures.

1. Spillway. The visual inspection revealed the spillway is in good condition. Some minor cracking was observed along the left spillway wingwall (see Photograph 3). No other deficiencies were noted (see Photographs 1 and 2).

2. Outlet Works. The outlet works are in excellent condition. The interior of the 4-foot square box culvert was inspected. It was noted that all joints were sealed and no cracking or leakage was in evidence. No signs of concrete deterioration were observed on the interior or exterior surfaces of the control tower. The 36-inch diameter slide gate was operated in the presence of the inspection team and is considered to be in excellent condition (see Photographs 4, 5, 6, and 7).

d. Reservoir Area. The general area surrounding Rose Valley Lake is comprised of gentle to moderate slopes immediately around the lake and steep slopes in the more distant reaches of the watershed. The immediate slopes are primarily cultivated while the distant slopes are heavily forested.

e. Downstream Channel. The channel downstream of Rose Valley Lake Dam is characterized as a narrow, primarily wooded valley with steep confining slopes. The first permanent structure situated near the streambed is a private residence located approximately one mile downstream of the embankment (see Photograph 8). Four more dwellings are

located along the stream within the next six miles prior to Mill Creek passing through the community of Warrentsville, Pennsylvania. The floodplain widens significantly near Warrentsville and remains fairly broad until it merges with Loyalsock Creek, near Williamsport, Pennsylvania about 12 miles downstream of the dam. It is estimated that many lives could be lost and significant damage could be incurred as the result of an embankment breach. Consequently, the hazard classification for this facility is considered to be high.

3.2 Evaluation.

The overall condition of the facility is considered excellent. The only deficiencies noted were minor cracking of the left spillway wingwall and poor drainage between the wingwall and left abutment. Both conditions require remedial attention.

SECTION 4 OPERATIONAL PROCEDURES

4.1 Normal Operating Procedure.

Rose Valley Lake Dam is essentially a self-regulating facility. Excess inflows are automatically discharged through the emergency spillway. Under normal operating conditions the outlet conduit is closed; however, the gate is opened two or three times a year to insure its operability.

The Pennsylvania Fish Commission has developed a formal Operation and Maintenance Manual for this facility that establishes both routine and emergency operating procedures.

4.2 Maintenance of Dam.

Formal procedures and guidelines for the complete maintenance of this facility are contained in the Operation and Maintenance Manual. The manual includes a formal maintenance checklist covering the entire facility.

4.3 Maintenance of Operating Facilities.

See Section 4.2 above.

4.4 Warning System.

A "Flood Emergency Operation Procedure" has been incorporated into the Operation and Maintenance Manual. The plan is a coordinated effort involving the Pennsylvania Fish Commission, PennDER, and the Lycoming County Emergency Management Agency (EMA, civil defense). A detailed evacuation plan is currently being developed by the EMA which, when complete, will become part of this plan.

4.5 Evaluation.

The operation and maintenance of Rose Valley Lake Dam has been formally established through the Operation and Maintenance Manual developed by the Pennsylvania Fish Commission. A formal warning system for the protection of downstream residents is available and has been incorporated into this manual although a detailed evacuation plan has not yet been prepared.

SECTION 5 HYDROLOGIC/HYDRAULIC EVALUATION

5.1 Design Data.

Calculations contained in Pennsylvania Fish Commission files indicate that the hydrologic and hydraulic design of Rose Valley Lake Dam was based on the Pennsylvania "C" Curve along with procedures and guidelines contained in the texts, "Design of Small Dams" by the U. S. Bureau of Reclamation, and "Handbook of Applied Hydraulics" by Davis and Sorensen.

The data indicate that the spillway design flow from the "C" Curve is 3970 cfs. The maximum spillway discharge capacity as computed by our analysis is 4620 cfs (see Appendix D, Sheet 10).

5.2 Experience Data.

Daily records of reservoir levels and/or spillway discharges are not available. The general appearance of the facility suggests adequate past performance.

5.3 Visual Observations.

On the date of inspection, no conditions were observed that would indicate the spillway could not perform satisfactorily during a flood event within the limits of its design capacity.

5.4 Method of Analysis.

The facility has been analyzed in accordance with the procedures and guidelines established by the U. S. Army, Corps of Engineers, Baltimore District, for Phase I hydrologic and hydraulic evaluations. The analysis has been performed utilizing a modified version of the HEC-1 program developed by the U. S. Army, Corps of Engineers, Hydrologic Engineering Center, Davis, California. Analytical capabilities of the program are briefly outlined in the preface contained in Appendix D.

5.5 Summary of Analysis

- a. Spillway Design Flood (SDF). In accordance with

procedures and guidelines contained in the National Guidelines for Safety Inspection of Dams for Phase I Investigations, the Spillway Design Flood (SDF) for Rose Valley Lake Dam is the PMF (Probable Maximum Flood). This classification is based on the relative size of the dam (intermediate), and the potential hazard of dam failure to downstream developments (high).

b. Results of Analysis. Rose Valley Lake Dam was evaluated under near normal operating conditions. That is, the reservoir was initially at its normal pool or spillway elevation of approximately 1235.0, with the spillway weir discharging freely. The outlet conduit was considered to be non-functional for the purpose of analysis, since the flow capacity of the conduit is not such that it would significantly increase the total discharge capabilities of the facility. The spillway consists of a rectangular, concrete chute channel with discharges controlled by a flat crested trapezoidal shaped weir. All pertinent engineering calculations relative to the evaluation of this facility are provided in Appendix D.

Overtopping analysis (using the Modified HEC-1 Computer Program) indicated that the discharge/storage capacity of Rose Valley Lake Dam can accommodate storms in excess of the PMF (SDF) without embankment overtopping. The peak PMF inflow of approximately 9340 cfs was greatly attenuated by the discharge/storage capabilities of the dam and reservoir, such that the resulting peak outflow was about 4060 cfs. The peak outflow is, thus, less than the spillway capacity calculated to be 4620 cfs. Under the PMF event, the reservoir level rose to elevation 1240.5, or about 0.5 feet below the low top of dam elevation of 1241.0 (Appendix D, Summary Input/Output Sheets, Sheet C).

5.6 Spillway Adequacy.

Rose Valley Lake Dam was found to be capable of passing and/or storing the inflow from its SDF (the PMF), and therefore its spillway is considered to be adequate.

SECTION 6
EVALUATION OF STRUCTURAL INTEGRITY

6.1 Visual Observations.

a. Embankment. Based on visual observations, the embankment appears to be in excellent structural condition. No deficiencies were noted with regards to the main structure. The poor drainage condition observed at the left abutment, adjacent the left spillway wingwall, is an apparent construction oversight. Design drawings indicate a trench drain was to be installed along the left embankment-abutment contact, but, was apparently overlooked. Excessive hydrostatic and/or ice pressures behind the left spillway wingwall could develop because of this poorly drained condition and could result in damage to the spillway structure if left uncorrected.

b. Appurtenant Structures.

1. Spillway. The spillway appears to be structurally well designed and currently in good condition. Cracking observed in the left spillway wingwall is considered minor at this time. Nevertheless, concrete cracks should be regularly filled and/or sealed with epoxy to forestall continuing deterioration.

2. Outlet Works. The outlet works, which include both the control tower riser and 4-foot square discharge culvert, are considered to be in excellent condition. No deficiencies were noted.

6.2 Design and Constrution Techniques.

Available design data indicates that the facility has been adequately designed in conformance with modern accepted engineering practice. Many of its features have been repeatedly incorporated into similar Pennsylvania Fish Commission designs and have proven their reliability.

Discussions with Fish Commission representatives revealed the project was finished in a timely manner and that no significant problems were incurred during construction.

6.3 Past Performance.

According to Pennsylvania Fish Commission personnel, the facility has operated virtually problem-free throughout its eight year history.

6.4 Seismic Stability.

The dam is located in Seismic Zone No. 1 and may be subject to minor earthquake induced dynamic forces. As the facility appears well constructed and sufficiently stable, it is believed that it can withstand the expected dynamic forces; however, no calculations and/or investigations were performed to confirm this belief.

SECTION 7
ASSESSMENT AND RECOMMENDATIONS FOR REMEDIAL MEASURES

7.1 Dam Assessment.

a. Safety. The visual inspection, operational history, and available engineering data indicate the facility is in excellent condition.

The size classification of the facility is intermediate and its hazard classification is considered to be high. In accordance with the recommended guidelines, the Spillway Design Flood (SDF) for the facility is the PMF (Probable Maximum Flood). Results of the hydrologic and hydraulic analysis indicate the facility is capable of passing and/or storing the PMF. Consequently, its spillway is considered adequate.

b. Adequacy of Information. The available data are considered sufficient to make a reasonable Phase I assessment of the facility.

c. Urgency. The recommendations listed below should be implemented immediately.

d. Necessity for Additional Investigations. No additional investigations are currently deemed necessary.

7.2 Recommendations/Remedial Measures.

It is recommended that the owner immediately:

a. Provide positive drainage for the area between the spillway wingwall and left abutment hillside.

b. Repair and seal all concrete cracks observed along the left spillway wingwall.

APPENDIX A

VISUAL INSPECTION CHECKLIST AND FIELD SKETCHES

CHECK LIST VISUAL INSPECTION PHASE 1

NAME OF DAM Rose Valley Lake Dam STATE Pennsylvania COUNTY Lycoming
NDI # PA - 01127 PENNDR # 41-97
TYPE OF DAM Earth SIZE Intermediate
DATE(S) INSPECTION 23 April 1980 WEATHER Sunny
POOL ELEVATION AT TIME OF INSPECTION 1235.1 Feet M.S.L.
TAILWATER AT TIME OF INSPECTION N/A M.S.L.
HAZARD CATEGORY High
TEMPERATURE 70° @ 1:30 p.m.

INSPECTION PERSONNEL

B. M. Mihalcin
D. J. Spaeder
D. L. Bonk
W. J. Veon

OWNER REPRESENTATIVES

Pennsylvania Fish Commission
E. Jon Grindall
D. O'Neill
E. Smith
C. Hess

OTHERS

RECORDED BY D. L. Bonk

EMBANKMENT

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA · 01127
SURFACE CRACKS	None observed.	
UNUSUAL MOVEMENT OR CRACKING AT OR BEYOND THE TOE	None observed.	
SLOUGHING OR EROSION OF EMBANKMENT AND ABUTMENT SLOPES	None observed.	
VERTICAL AND HORIZONTAL ALIGNMENT OF THE CREST	Horizontal - good. Vertical - good.	
RIPRAP FAILURES	Limestone and sandstone riprap protects the entire upstream embankment face. Good condition.	
JUNCTION OF EMBANKMENT AND ABUTMENT, SPILLWAY AND DAM	Good condition. Seepage observed through left abutment rock (estimated \approx 2-3 gpm). Water collects between left spillway wingwall and abutment due to poor drainage.	

EMBANKMENT

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 01127
DAMP AREAS IRREGULAR VEGETATION (LUSH OR DEAD PLANTS)	None observed along downstream embankment face to toe.	
ANY NOTICEABLE SEEPAGE	Seepage observed through left abutment rock (estimated \approx 2-3 gpm). No seepage through embankment observed.	
STAFF GAGE AND RECORDER	None.	
DRAINS	Two drains observed through outlet channel wingwalls at downstream toe. Right drain is wet with no discernable flow. Left drain discharging at less than 1/2 gpm.	
ROCK OUTCROPS	Left abutment - Horizontally bedded red and blue-gray sandstones and siltstones.	

OUTLET WORKS

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 01127
INTAKE STRUCTURE	Intake submerged. Control tower in excellent condition. No evidence of concrete deterioration.	
OUTLET CONDUIT (CRACKING AND SPALLING OF CON- CRETE SURFACES)	Good condition. Interior joints have been sealed. No cracks or leakage observed.	
OUTLET STRUCTURE	Excellent condition.	
OUTLET CHANNEL	Rock lined trapezoidal shaped channel. Good condition.	
GATE(S) AND OPERA- TIONAL EQUIPMENT	Gate operated in the presence of the inspection team. Good condition.	

EMERGENCY SPILLWAY

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA- 01127
TYPE AND CONDITION	Uncontrolled, rectangular, concrete chute channel located at left abutment. Good condition. Flows are controlled by a trapezoidal shaped, flat crested weir.	
APPROACH CHANNEL	Rock lined.	
SPILLWAY CHANNEL AND SIDEWALLS	Right wingwall and channel floor are in excellent condition. Minor cracking observed in left wingwall. Evidence of some leakage through the cracks observed.	
STILLING BASIN PLUNGE POOL	60-foot by 60-foot concrete stilling basin with vertical wingwalls.	
DISCHARGE CHANNEL	Rock lined, trapezoidal shaped channel.	
BRIDGE AND PIERS EMERGENCY GATES	Small concrete roadway bridge across channel immediately downstream of embankment.	

SERVICE SPILLWAY


ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 01127
TYPE AND CONDITION	N/A.	
APPROACH CHANNEL	N/A.	
OUTLET STRUCTURE	N/A.	
DISCHARGE CHANNEL	N/A.	

INSTRUMENTATION

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDI# PA - 01127
MONUMENTATION SURVEYS	None observed.	
OBSERVATION WELLS	None.	
WEIRS	None.	
PIEZOMETERS	None.	
OTHERS		

RESERVOIR AREA AND DOWNSTREAM CHANNEL

ITEM	OBSERVATIONS/REMARKS/RECOMMENDATIONS	NDH# PA - 01127
SLOPES: RESERVOIR	Immediate slopes are gentle to moderate and primarily cultivated. Distant slopes are steep and heavily forested.	
SEDIMENTATION	None observed.	
DOWNSTREAM CHANNEL (OBSTRUCTIONS, DEBRIS, ETC.)	Concrete and masonry roadbridge spans channel immediately downstream of the embankment.	
SLOPES: CHANNEL VALLEY	The channel downstream is characterized as a narrow, primarily wooded valley with steep confining slopes. The floodplain widens about 6 miles downstream near the community of Warrentonville, Pennsylvania and remains fairly broad until the stream merges with Loyalsock Creek about 12 miles downstream.	
APPROXIMATE NUMBER OF HOMES AND POPULATION	Five dwellings are located near the streambed within 6 miles of the embankment prior to the stream passing through the community of Warrentonville, Pennsylvania. It is estimated that many lives could be lost and significant damage incurred as the result of an embankment breach.	



ROSE VALLEY LAKE DAM
GENERAL PLAN - FIELD INSPECTION NOTES

ROSE VALLEY LAKE DAM

PROFILE OF DAM CREST
FROM FIELD SURVEY

LOW TOP OF DAM @ TOP OF
SPILLWAY WINGWALLS, ELEV. 1241.0

1245.0

1240.0

1235.0

LEFT
ABUTMENT

RIGHT
ABUTMENT

SPILLWAY CREST,
ELEV. 1235.0

SCALE

VERTICAL: 1" = 10 FT

HORIZONTAL: 1" = 100 FT

APPENDIX B
ENGINEERING DATA CHECKLIST

**CHECK LIST
ENGINEERING DATA
PHASE I**

NAME OF DAM Rose Valley Lake Dam

ITEM	REMARKS	NDI# PA - 01127
PERSONS INTERVIEWED AND TITLE	Pennsylvania Fish Commission (PFC) E. Jon Grindall - Senior Project Engineer D. O'Neill - Maintenance Supervisor E. Smith - Chief of Maintenance Construction C. Hess - Area Five Manager	
REGIONAL VICINITY MAP	See Appendix E, Figure 1.	
CONSTRUCTION HISTORY	Designed by Pennsylvania Fish Commission. Constructed in 1971-1972 by Giffin Construction Company of LeRaysville, Pennsylvania.	
AVAILABLE DRAWINGS	Complete set of 24 drawings available from both the PennDER and the Pennsylvania Fish Commission.	
TYPICAL DAM SECTIONS	See Appendix E, Figures 3 and 5.	
OUTLETS: PLAN DETAILS DISCHARGE RATINGS	See Appendix E, Figures 3 and 10. Discharge rating curves are not available.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	ND# PA -
SPILLWAY: PLAN SECTION DETAILS	See Appendix E, Figures 3, 6, 7 and 8.	
OPERATING EQUIP. MENT PLANS AND DETAILS	See Appendix E, Figure 9.	
DESIGN REPORTS	No formal design reports available. A preliminary engineering report by E. R. Miller, dated 1965, is contained in PFC files. Design calculations, specifications, daily construction reports and photographs are also available in PFC files.	
GEOLOGY REPORTS	"Geology of the Proposed Mill Creek Dam Site" by William D. Sevon of The Pennsylvania Geological Survey is contained in PFC files,	
DESIGN COMPUTATIONS: HYDROLOGY AND HYDRAULICS STABILITY ANALYSES SEEPAGE ANALYSES	Weir measurements, Stage/Storage Curves and Hydrological Study are contained in PFC files.	
MATERIAL INVESTIGATIONS: BORING RECORDS LABORATORY TESTING FIELD TESTING	Test Boring Report, Soils and Testing of Harrisburg, Pennsylvania, dated 1970, contained PFC and PenbDER files. Soils and concrete field testing data are also available from the PFC.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	ND# PA - 01127
BORROW SOURCES	Within reservoir. See Appendix E, Figure 2.	
POST CONSTRUCTION DAM SURVEYS	None.	
POST CONSTRUCTION ENGINEERING STUDIES AND REPORTS	None.	
HIGH POOL RECORDS	No formal records are available.	
MONITORING SYSTEMS	None.	
MODIFICATIONS	None.	

**CHECK LIST
ENGINEERING DATA
PHASE I
(CONTINUED)**

ITEM	REMARKS	NDI# PA - 01127
PRIOR ACCIDENTS OR FAILURES	None.	
MAINTENANCE: RECORDS MANUAL	Regular maintenance guidelines are outlined in the Operation and Maintenance Manual available from PFC.	
OPERATION: RECORDS MANUAL	Outlet conduit open two or three times per year to insure its operability. Operation and Maintenance Manual available from PFC. No formal operating records are available.	
OPERATIONAL PROCEDURES	Self-regulating.	
WARNING SYSTEM AND/OR COMMUNICATION FACILITIES	Incomplete warning system contained in Operation and Maintenance Manual. PFC is currently working with local civil defense and other emergency action groups to refine and complete the system.	
MISCELLANEOUS		

GAI CONSULTANTS, INC.

**CHECK LIST
HYDROLOGIC AND HYDRAULIC
ENGINEERING DATA**

NDI ID # 01127
PENNDER ID # 41-97

SIZE OF DRAINAGE AREA: 3.4 square miles.
ELEVATION TOP NORMAL POOL: 1235.0 STORAGE CAPACITY: 3940 acre-feet.
ELEVATION TOP FLOOD CONTROL POOL: - STORAGE CAPACITY: -
ELEVATION MAXIMUM DESIGN POOL: 1240.5 STORAGE CAPACITY: 6260 acre-feet.
ELEVATION TOP DAM: 1241.0 STORAGE CAPACITY: 6500 acre-feet.

SPILLWAY DATA

CREST ELEVATION: 1235.0 feet.
TYPE: Uncontrolled, rectangular, concrete chute channel.
CREST LENGTH: 80 feet.
CHANNEL LENGTH: 164.5 feet. (Does not include approach area).
SPILLOVER LOCATION: Left abutment.
NUMBER AND TYPE OF GATES: None.

OUTLET WORKS


TYPE: 4' by 4' reinforced concrete box culvert.
LOCATION: Near center of embankment.
ENTRANCE INVERTS: 1215.5 feet.
EXIT INVERTS: 1215.0 feet.
EMERGENCY DRAWDOWN FACILITIES: 36-inch diameter slide gate and removable stop logs.

HYDROMETEOROLOGICAL GAGES

TYPE: None.
LOCATION: -
RECORDS: -

MAXIMUM NON-DAMAGING DISCHARGE: Not known.

APPENDIX C
PHOTOGRAPHS



ROSE VALLEY LAKE DAM
PHOTOGRAPH KEY MAP

PHOTOGRAPH 1 View of the embankment as seen from the left abutment.

PHOTOGRAPH 2 View of the spillway looking upstream as seen from just beyond the stilling basin.

PHOTOGRAPH 3 View of minor cracking in the left spillway wingwall.

PHOTOGRAPH 4 View of the control tower riser located along the upstream embankment slope.



2



4



1



3

PHOTOGRAPH 5 Interior view of the control tower riser and slide gate operator.

PHOTOGRAPH 6 View of the outlet structure located at the downstream embankment toe.

PHOTOGRAPH 7 View of the area immediately downstream of the embankment as seen from the embankment crest.

PHOTOGRAPH 8 View of the first downstream residence in the valley below the dam located approximately one mile from the embankment.



8



7



6



5

APPENDIX D
HYDROLOGY AND HYDRAULICS ANALYSES

PREFACE

The modified HEC-1 program is capable of performing two basic types of hydrologic analyses: 1) the evaluation of the overtopping potential of the dam; and 2) the estimation of the downstream hydrologic-hydraulic consequences resulting from assumed structural failures of the dam. Briefly, the computational procedures typically used in the dam overtopping analysis are as follows:

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir to determine if the event(s) analyzed would overtop the dam.
- c. Routing of the outflow hydrograph(s) from the reservoir to desired downstream locations. The results provide the peak discharge(s), time(s) of the peak discharge(s), and the maximum stage(s) of each routed hydrograph at the downstream end of each reach.

The evaluation of the hydrologic-hydraulic consequences resulting from an assumed structural failure (breach) of the dam is typically performed as shown below.

- a. Development of an inflow hydrograph(s) to the reservoir.
- b. Routing of the inflow hydrograph(s) through the reservoir.
- c. Development of a failure hydrograph(s) based on specified breach criteria and normal reservoir outflow.
- d. Routing of the failure hydrograph(s) to desired downstream locations. The results provide estimates of the peak discharge(s), time(s) to peak and maximum water surface elevations of failure hydrographs for each location.

HYDROLOGY AND HYDRAULIC ANALYSIS DATA BASE

NAME OF DAM: ROSE VALLEY LAKE DAM

PROBABLE MAXIMUM PRECIPITATION (PMP) = 22.2 INCHES/24 HOURS (1)

STATION	1	2	3
STATION DESCRIPTION	Rose Valley Lake Dam		
DRAINAGE AREA (SQUARE MILES)	3.4		
CUMULATIVE DRAINAGE AREA (SQUARE MILES)	-		
ADJUSTMENT OF PMP FOR DRAINAGE AREA LOCATION (2) (1)			
6 HOURS	118		
12 HOURS	127		
24 HOURS	136		
48 HOURS	143		
72 HOURS	145		
SNYDER HYDROGRAPH PARAMETERS			
ZONE (2)	17		
C_p (3)	0.45		
C_t (3)	1.13		
L' (MILES) (4)	1.2		
$t_p = C_t (L')^{0.6}$ (HOURS)	1.26		
SPILLWAY DATA			
CREST LENGTH (FEET)	80		
FREEBOARD (FEET)	6.0		

(1) HYDROMETEOROLOGICAL REPORT 40, U.S. Weather Bureau, 1965.

(2) HYDROLOGIC ZONE DEFINED BY CORPS OF ENGINEERS, BALTIMORE DISTRICT, FOR DETERMINATION OF SNYDER COEFFICIENTS (C_p AND C_t).

(3) SNYDER COEFFICIENTS

(4) L' = LENGTH OF LONGEST WATERCOURSE FROM RESERVOIR INLET TO BASIN DIVIDE.

SUBJECT DAM SAFETY INSPECTION
ROSE VALLEY LAKE DAM
BY ZJS DATE 5-22-79 PROJ. NO. 79-203-127
CHKD. BY WJV DATE 6-12-80 SHEET NO. 1 OF 13



DAM STATISTICS

- HEIGHT OF DAM = 26 FT

(FIELD MEASURED: INVERT OF OUTLET
TO LOW TOP OF DAM)

- NORMAL POOL STORAGE CAPACITY = 3940 AC-FT

(SHEET 3)

- DESIGN FLOOD POOL STORAGE CAPACITY = 6260 AC-FT

(SHEET 3)

- MAXIMUM POOL STORAGE CAPACITY = 6500 AC-FT

(SHEET 3)

(@ LOW TOP OF DAM)

- DRAINAGE AREA = 3.4 SQ MI.

(PLANIMETERED ON USGS 7.5' TOPO MAPS:
BOOMES, MONTGOMERY COUNTY, AND
TROUT RUN, PA)

ELEVATIONS:

TOP OF DAM (DESIGN) = 1241.0

(FIG. 3)

TOP OF DAM (FIELD) = 1241.0

DESIGN FLOOD POOL = 1240.5

(SHEET 4)

NORMAL POOL = 1235.0

(SHEET 4)

SPILLWAY CREST = 1235.0

(FIG. 6)

UPSTREAM INLET INVERT = 1215.5

(FIG. 10)

DOWNSTREAM OUTLET INVERT (DESIGN) = 1215.0

(FIG. 10)

DOWNSTREAM OUTLET INVERT (FIELD) = 1215.0

STREAMBED @ DAM CENTERLINE = 1215

(ESTIMATED, FIG. 3)

SUBJECT DAM SAFETY INSPECTION
ROSE VALLEY LAKE DAM
 BY RTS DATE 5-30-80 PROJ. NO. 79-203-127
 CHKD. BY WJV DATE 6-12-80 SHEET NO. 2 OF 13



DAM CLASSIFICATION

DAM SIZE : INTERMEDIATE (REF 1, TABLE 1)
 HAZARD CLASSIFICATION : HIGH (FIELD OBSERVATION)
 REQUIRED SDF : PMF (REF 1, TABLE 3)

HYDROGRAPH PARAMETERS

LENGTH OF LONGEST WATERCOURSE FROM RESERVOIR INLET
 TO BASIN DIVIDE : $L' = \underline{1.2}$ MILES

(MEASURED ON U.S. TOPO QUADS :
 BOONIES, MONTICELLO NORTH,
 AND TROUT RUN, PA)

$$C_p = \underline{2.45}$$

$$C_e = \underline{1.13}$$

(SNYDER PARAMETERS SUPPLIED BY C.O.E.;
 ZONE 17, SUSQUEHANNA RIVER BASIN)

$$\text{SNYDER'S STANDARD LAG} = C_e (L')^{0.6}$$

$$t_p = 1.13 (1.2)^{0.6} = \underline{1.26} \text{ HRS}$$

NOTE : SINCE L_{CA} , THE LENGTH OF THE LONGEST WATERCOURSE FROM THE
 DAM TO A POINT OPPOSITE THE BASIN CENTROID, IS LESS THAN THE LENGTH
 OF THE RESERVOIR (BY INSPECTION; SEE FIGURE 1), THE SNYDER STANDARD
 LAG IS ESTIMATED AS $t_p = C_e (L')^{0.6}$ HOURS (AS PER C.O.E.). HYDROGRAPH
 VARIABLES USED HERE ARE DEFINED IN REF 2, IN SECTION ENTITLED "SNYDER
 SYNTHETIC UNIT HYDROGRAPH."


SUBJECT DAM SAFETY INSPECTION
ROSE VALLEY LAKE DAM
 BY RJS DATE 5-27-80 PROJ. NO. 73-303-167
 CHKD. BY WJV DATE 6-12-80 SHEET NO. 3 OF 13



ELEVATION-STORAGE RELATIONSHIP

THE FOLLOWING ELEVATION-STORAGE VALUES ARE TAKEN FROM
 THE STORAGE-AREA CURVES (PROVIDED BY OWNER) GIVEN ON SHEET 4.

	RESERVOIR ELEVATION (FT)	STORAGE (AC-FT)
	1215.5	0
	1220.0	130
	1225.0	780
	1230.0	2160
(NORMAL POOL)	1235.0	3943
	1236.0	4330
	1237.0	4740
	1238.0	5160
	1239.0	5590
	1240.0	6030
(DESIGN FLOOD POOL)	1240.5	6260
(LOW TOP OF DAM)	1241.0	6500
	1242.0	6980
	1243.0	7470
	1244.0	7960
	1245.0	8450



SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY DJS DATE 5-27-80 PROJ. NO. 79-303-127

CHKD. BY WJV DATE 6-12-80 SHEET NO. 5 OF 13



Engineers • Geologists • Planners
Environmental Specialists

PMP CALCULATIONS

- FROM REF 9, FIG. 2, OBTAIN PMP VALUE FOR A BASIN OF DRAINAGE AREA 200 SQUARE MILES, AND A DURATION OF 24 HOURS:

$$P = \underline{22.2} \text{ INCHES}$$

- FROM REF 9, FIG. 1, THE GEOGRAPHIC ADJUSTMENT FACTOR = 100%
(LOCATION N 41° 33.7', W 76° 59.9')

- AREA CORRECTION FACTOR (REF 9):

DURATION (HRS):	6	12	24	48	72
FACTOR (%):	117.5	127.0	136.0	142.5	145.0

- TOTAL CORRECTION FACTOR (100% X AREA CORRECTION FACTOR)

DURATION (HRS):	6	12	24	48	72
FACTOR (%):	118	127	136	143	145

- HOP BROOK FACTOR (ADJUSTMENT FOR BASIN SHAPE AND FOR THE LESSER LIKELIHOOD OF A SEVERE STORM CENTERING OVER A SMALL BASIN) FOR A DRAINAGE AREA OF 2.4 SQUARE MILES IS 0.82

(REF 4, p. 48)

SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY WJS DATE 5-27-80 PROJ. NO. 79-203-137


CHKD. BY WJV DATE 6-12-90 SHEET NO. 6 OF 13




Engineers • Geologists • Planners
Environmental Specialists

SPILLWAY CAPACITY

PROFILE:



CROSS-SECTION:




(SKETCHES BASED ON FIELD MEASUREMENTS
AND DESIGN DRAWINGS, PGS. 6-9)

SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY DJS DATE 6-5-80 PROJ. NO. 79-203-127

CHKD. BY WJV DATE 6-12-80 SHEET NO. 7 OF 13



THE SPILLWAY CONSISTS OF A RECTANGULAR CONCRETE CHUTE CHANNEL WITH DISCHARGES CONTROLLED BY A FLAT-CRESTED TRAPEZOIDAL-SHAPED WEIR. DISCHARGE OVER THE WEIR CAN BE ESTIMATED BY THE RELATIONSHIP

$$Q = CLH^{3/2} \quad (\text{REF 5, p. 5-23})$$

WHERE Q = DISCHARGE, IN CFS,
 C = DISCHARGE COEFFICIENT,
 L = LENGTH OF WEIR CREST = 80 FT,
 H = HEAD, IN FT.

THE COEFFICIENT OF DISCHARGE CORRESPONDING TO A HEAD OF 1.5 FT IS 3.82 (REF 5, TABLE 5-9). AS THE HEAD ON THE WEIR BECOMES SMALL, DISCHARGE IS REDUCED DISPROPORTIONATELY, DUE TO THE ROUGHNESS AND THE CONTACT PRESSURE BETWEEN THE WATER AND THE WEIR SURFACE. THUS, THE DISCHARGE COEFFICIENT (C) TAKES ON A LOWER VALUE. THE OPPOSITE TREND OCCURS FOR INCREASING HEADS. THEREFORE, THE DISCHARGE COEFFICIENT WILL BE ADJUSTED ACCORDING TO FIG. 250, REF 4, ASSUMING THAT THE RELATIONSHIPS FOR OGEE WEIRS CAN BE APPLIED TO THIS TRAPEZOIDAL-SHAPED WEIR.

AT LOW TOP OF DAM, EL. 1341.0,
 $H_1 = 6.0$ FT,
 ASSUMING $H_0 = 1.5$ FT (SEE ABOVE),

$$\frac{H_1}{H_0} = \frac{6}{1.5} = 4.0.$$

FROM FIG. 250, REF 4, $C/C_0 = 1.07$; ASSUMING $C_0 = 3.82$,
 $C = 1.07 \times 3.82 = 4.09$

$$\therefore Q_{\text{INITIAL}} = (4.09)(80)(6)^{3/2} = 1309 \text{ CFS}$$

SUBJECT DAM SAFETY INSPECTION
ROSE VALLEY LAKE DAM
 BY ZIS DATE 6-5-80 PROJ. NO. 79-203-127
 CHKD. BY WJV DATE 6-12-80 SHEET NO. 8 OF 13



→ ESTIMATE APPROACH CHANNEL LOSSES AT ELEV. 1241.0 :

- AVG. LENGTH OF APPROACH CHANNEL = 210 FT (FIG. 3)

- AVG. DEPTH OF APPROACH CHANNEL = $H + P$
 $= 6.0 + 2.5 = \underline{8.5}$ FT

- AVG. WIDTH OF APPROACH CHANNEL = 145 FT (FIG. 3)

- RIGHT SIDE-WALL → VERTICAL

- LEFT SIDE-SLOPE = 2H:1V (FIG. 7)

- AVERAGE HEIGHT OF RIGHT SIDEWALL = $[(10 \times 8.5) + (27 \times \frac{8.5}{2})] / 37$
 $= \underline{5.4}$ FT

- AVERAGE FLOW AREA IN APPROACH CHANNEL = $(145 \times 8.5) + [\frac{1}{2} \times (2 \times 8.5)(8.5)]$
 $= \underline{1305}$ FT²

- AT ELEV. 1241.0, $H_1 = 6.0$,

$Q = \underline{4809}$ CFS (SEE SHEET 7)

- AVG. VELOCITY IN APPROACH CHANNEL →
 $V_a = \frac{Q}{A} = \frac{4809}{1305} = \underline{3.7}$ FT/SEC

- AVG. APPROACH VELOCITY HEAD →

$$h_a = \frac{V_a^2}{2g} = \frac{3.7^2}{64.4} = \underline{0.2} \text{ FT}$$

- ASSUMING THE APPROACH CHANNEL ENTRANCE LOSS = $0.1 h_a$, (REF 4, p. 372,

$h_e = \text{ENTRANCE LOSS} = (0.1)(0.2) = \underline{0.02}$ FT

SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY RJS DATE 6-5-80 PROJ. NO. 79-203-127

CHKD. BY WJV DATE 6-12-80 SHEET NO. 9 OF 13



Engineers • Geologists • Planners
Environmental Specialists

APPROACH CHANNEL FRICTION LOSS, h_F :

$$h_F = \left[\frac{V_a n}{(1.49) R^{2/3}} \right]^2 \times L$$

WHERE L = APPROACH CHANNEL LENGTH = 210 FT,

n = MANNING'S ROUGHNESS COEFFICIENT = 0.040 (FIELD ESTIMATE),

R = HYDRAULIC RADIUS = FLOW AREA / WETTED PERIMETER.

$$\begin{aligned} \text{WETTED PERIMETER} = P_w &= 145 + 5.4 + \sqrt{(8.5)^2 + (2 \times 8.5)^2} \\ &= \underline{169.4 \text{ FT}} \end{aligned}$$

$$\therefore R = \frac{1305 \text{ FT}^2}{169.4 \text{ FT}} = \underline{7.7 \text{ FT}}$$

$$h_F = \left[\frac{(3.7)(0.040)}{(1.49)(7.7)^{2/3}} \right]^2 \times 210 = \underline{0.14 \text{ FT}}$$

$$\begin{aligned} \therefore \text{TOTAL APPROACH LOSS} = h_e + h_F &= 0.02 + 0.14 \\ &= \underline{0.16 \text{ FT}} \end{aligned}$$

$$\text{— ACTUAL EFFECTIVE HEAD} = 6.0 - 0.16 = \underline{5.84 \text{ FT}}$$

\therefore @ ELEV 1241.0, SPILLWAY CAPACITY \rightarrow

$$Q = (4.09)(80)(5.84)^{1.5} = 4618 = \underline{4620 \text{ CFS}}$$

— FOR HEADS OTHER THAN 6.0, APPROACH CHANNEL LOSSES WILL BE ASSUMED TO BE PROPORTIONAL TO THAT AT $H = 6.0$:

$$h_L = 0.16 \left(\frac{H}{6.0} \right)$$

WHERE h_L = TOTAL APPROACH CHANNEL LOSS, IN FT,

H = RESERVOIR ELEVATION - 1235.0.

SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY WJS DATE 6-6-80 PROJ. NO. 79-203-127

CHKD. BY WJV DATE 6-12-90 SHEET NO. 10 OF 13



Engineers • Geologists • Planners
Environmental Specialists

SPILLWAY RATING TABLE

RESERVOIR ELEVATION (FT)	H (FT)	H/H_0	C/C_0	C	H/H_1	h_L (FT)	H_e (FT)	Q ^⑦ CFS
1235.0	—	—	—	—	—	—	—	0
1236.0	1.0	—	—	3.52	0.17	0.33	0.97	270
1237.0	2.0	1.33	1.04	3.97	0.33	0.05	1.95	860
1238.0	3.0	2.00	1.07	4.09	0.50	0.08	2.92	1630
1239.0	4.0	2.67	1.07	4.09	0.67	0.11	3.89	2510
1240.0	5.0	3.33	1.07	4.09	0.83	0.13	4.87	3520
(DESIGN FLOOD POOL)	1240.5	5.5	3.67	1.07	4.09	0.92	5.35	4050
(LOW TOP OF DAM)	1241.0	6.0	4.00	1.07	4.09	1.00	5.84	4620
	1241.5	6.5	4.33	1.07	4.09	1.08	6.33	5210
	1242.0	7.0	4.67	1.07	4.09	1.17	6.81	5810
	1242.5	7.5	5.00	1.07	4.09	1.25	7.30	6450
	1243.0	8.0	5.33	1.07	4.09	1.33	7.79	7110
	1244.0	9.0	6.00	1.07	4.09	1.50	8.76	8480
	1245.0	10.0	6.67	1.07	4.09	1.67	9.73	9930

① H_0 = DESIGN HEAD ; ASSUME $H_0 = 1.5$ FT (SEE SHEET 7).

② FROM REF 4, FIG. 250.

③ $C = (C/C_0) \times 3.82$; AT $H = 1.0$, $C = 3.52$, FROM REF 5, TABLE 5-9.

④ $H_1 = 6.0$ FT (SEE SHEETS 7-9).

⑤ $h_L = 0.16 (H/H_1)$

⑥ H_e = EFFECTIVE HEAD = $H - h_L$

⑦ $Q = CLH_e^{3/2}$, $L = 80$ FT.

SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY DJS DATE 5-29-80 PROJ. NO. 79-203-127

CHKD. BY WJV DATE 6-12-80 SHEET NO. 11 OF 13



Engineers • Geologists • Planners
Environmental Specialists

EMBANKMENT RATING CURVE

ASSUME THAT THE EMBANKMENT BEHAVES ESSENTIALLY AS A BROAD-CRESTED WEIR WHEN OVERTOPPING OCCURS. THUS, THE DISCHARGE CAN BE ESTIMATED BY THE RELATIONSHIP

$$Q = CLH^{3/2} \quad (\text{REF 5, p. 5-23})$$

WHERE Q = DISCHARGE OVER EMBANKMENT, IN CFS,
 L = LENGTH OF EMBANKMENT OVERTOPPED,
 H = HEAD; IN THIS CASE IT IS THE AVERAGE "FLOW-AREA" WEIGHTED HEAD ABOVE THE CREST, WITH THE LOW TOP OF DAM AS THE DATUM;
 C = COEFFICIENT OF DISCHARGE, DEPENDENT UPON THE HEAD AND THE WEIR BREADTH.

LENGTH OF EMBANKMENT INUNDATED VS RESERVOIR ELEVATION:

<u>RESERVOIR ELEVATION</u> <u>(FT)</u>	<u>EMBANKMENT LENGTH</u> <u>(FT)</u>
1241.0	0
1241.1	35
1241.4	110
1241.5	335
1242.0	390
1242.5	440
1243.0	445
1244.0	460
1245.0	470

(BASED ON FIELD SURVEY -
USGS TOPO 7.5 - BODINES, CA
RT SIDE-SLOPES = 9:1,
LT SIDE-SLOPES = 4:1.)

SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY WJS DATE 5-29-80 PROJ. NO. 79-303-127

CHKD. BY WJV DATE 6-12-80 SHEET NO. 12 OF 13



Engineers • Geologists • Planners
Environmental Specialists

ASSUME THAT INCREMENTAL DISCHARGES OVER THE EMBANKMENT FOR SUCCESSIVE RESERVOIR ELEVATIONS ARE APPROXIMATELY TRAPEZOIDAL IN CROSS-SECTIONAL FLOW AREA. THEN ANY INCREMENTAL AREA OF FLOW CAN BE ESTIMATED AS $H_i [(L_1 + L_2)/2]$, WHERE L_1 = LENGTH OF OVERTOPPED EMBANKMENT AT HIGHER ELEVATION, L_2 = LENGTH AT LOWER ELEVATION, H_i = DIFFERENCE IN ELEVATIONS. THUS, THE TOTAL AVERAGE "FLOW-AREA" WEIGHTED HEAD CAN BE ESTIMATED AS $H_w = (TOTAL FLOW AREA / L_1)$.

EMBANKMENT RATING TABLE :

RESERVOIR ELEVATION (FT)	L_1 (FT)	L_2 (FT)	INCREMENTAL HEAD, H_i (FT)	INCREMENTAL FLOW AREA, A_i (FT ²)	TOTAL FLOW AREA, A_T (FT ²)	WEIGHTED HEAD, H_w (FT)	$\frac{H_w}{L}$	C	Q (CFS)
1241.0	0	-	-	-	-	-	-	-	0
1241.1	35	0	0.1	2	2	0.1	0.01	2.93	0
1241.4	110	35	0.3	22	24	0.2	2.01	2.97	30
1241.5	335	110	0.1	22	46	0.1	0.01	2.93	30
1242.0	390	335	0.5	181	227	0.6	0.24	3.23	550
1242.5	440	390	0.5	208	435	1.0	0.27	3.23	1330
1243.0	445	440	0.5	221	656	1.5	0.10	3.24	2490
1244.0	460	445	1.0	453	1109	2.4	0.16	3.26	5230
1245.0	470	460	1.0	465	1574	3.3	0.22	3.28	8630

① $A_i = H_i [(L_1 + L_2)/2]$

② $H_w = (A_T / L_1)$

③ L = BROADTH OF CREST ≈ 15 FT (FIELD MEASURED)

④ $C = f(H, L)$; FROM REF 12, FIG. 24.

⑤ $Q = CL H_w^{3/2}$

SUBJECT DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY RJS DATE 6-6-80 PROJ. NO. 79-203-127

CHKD. BY WJV DATE 6-12-90 SHEET NO. 13 OF 13



Engineers • Geologists • Planners
Environmental Specialists

TOTAL FACILITY RATING TABLE

RESERVOIR ELEVATION (FT)	Q _{SPILLWAY} (CFS)	Q _{EMBANKMENT} (CFS)	Q _{TOTAL} (CFS)
1235.0	0	-	0
1236.0	270	-	270
1237.0	860	-	860
1238.0	1630	-	1630
1239.0	2510	-	2510
1240.0	3520	-	3520
(DESIGN FLOOD POOL) 1240.5	4050	-	4050
(LOW TOP OF DAM) 1241.0	4620	0	4620
1241.5	5210	30	5240
1242.0	5810	550	6360
1242.5	6450	1330	7780
1243.0	7110	2490	9600
1244.0	8480	5230	13,710
1245.0	9930	8680	18,610

DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

BY DJS

DATE _____

6-12-80

PROJ. NO.

79-203-127

CHKD. BY DLB

DATE _____

6-13-80

SHEET NO

 A OF C



CONSULTANTS, INC.

**Engineers • Geologists • Planners
Environmental Specialists**

SUMMARY INPUT/OUTPUT

OVERTOPPING ANALYSIS

DAM SAFETY INSPECTION
RUSE VALLEY LAKE DAM *** OVERTOPPING ANALYSIS ***
15-MINUTE TIME STEP AND 72-HOUR STORM DURATION

JOB SPECIFICATION

NO	NH	NHIN	IDAY	INH	ININ	WCTC	IPLT	IPRT	NSTAN
100	0	15	0	0	0	0	0	0	0
			JUPEN	NPT	LROPT	TRACE			
			5	0	0	0			

MULTI-PLAN ANALYSES TO BE PERFORMED

```

PLAN= 1 NRTIO= 4 INRTIO= 1
      .50      .80      .90      1.00

```

[illegible]

SUB-AREA RUNOFF COMPUTATION

RESERVOIR INFLATION COMPUTATION

ISTAG	ICOMP	IECON	IUAPE	JPL1	JPAT	INAME	ISTAG	JAUTO
1	0	0	0	0	0	1	0	0

HYDROGRAPH DATA

	LUNG	TAREA	SNAP	THSDA	THSPC	RATIO	ISNUM	ISAME	LOCAL
ENYDGE	1	1.40	0.00	1.40	0.00	0.000	0	1	0

PR

SPFE	PMS	K6	K12	K24	K48	K96
0.00	22.20	110.00	127.00	136.00	143.00	145.00

INITIAL & CONSTANT RAINFALL
LOSSES AS PER C.O.E.

LOSS DATA

GROUP	STGR	ULTN	RIIL	FRAN	STWKS	RTICK	STMTL	CMSTL	ALSNX	WTJMP
0	0.00	0.00	1.00	0.00	0.00	1.00	1.00	0.05	0.00	0.00

INIT HYDROGRAPH DATA

UNIT MICROGRAPH DATA

TYPE	1.26	CP= .45	N/A= U	DATE FLOW PARAMETERS
				AS PER COE.

FILED AUG 30 1964

$\text{SHTO} = -1.50$	$\text{QRSHE} = -.05$	$\text{RHOE} = 2.00$
-----------------------	-----------------------	----------------------

UNIT	HYDROGRAPH	45 MIN-UP-PERIOD	UNDERRATES, LAC=	1.2% HOURS, CT=	.45	WID. ± 1.00
50.	216.	432.	637.	770.	619.	545.
21.	372.	328.	288.	254.	197.	134.
10.	104.	92.	81.	71.	63.	43.
33.	29.	26.	23.	18.	15.	12.
3.	8.	7.	6.	6.	7.	11.

gmi
CONSULTANTS, INC.

**Engineers • Geologists • Planners
Environmental Specialists**

[illegible]

(PMF)

HYDROGRAPH ROUTING

ROUTE THROUGH RESERVUIN

[illegible]

DAM SAFETY INSPECTION

ROSE VALLEY LAKE DAM

255


6-12-80

PROJ. NO. 79-203-127

DLB

6-13-80

SHEET NO. C OF C



**Engineers • Geologists • Planners
Environmental Specialists**

PEAK OUTFLOW IS

4059. AT TIME

PEAK DATA

ROSE VALLEY
LAKE
OUTFLOW

(PMF)

	PEAK	6-HOUR	24-HOUR	72-HOUR	TOTAL VOLUME
CFS	4059.	3610.	1842.	666.	19177.
CMS	115.	102.	19.	52.	520.
INCHES		9.88	20.16	21.85	21.85
MM		250.89	512.02	555.01	555.01
AC-FT		3654.	1790.	3960.	3960.
THOUS CU YD		2208.	4507.	4845.	4845.

SUMMARY OF DAM SAFETY ANALYSIS

RATIO OF PMF	MAXIMUM RESERVOIR W.S.ELEV	MAXIMUM DEPTH OVER DAM	MAXIMUM STORAGE AC-FT	MAXIMUM OUTFLOW CFS	DURATION OVER TOP HOURS	TIME OF MAX OUTFLOW HOURS	TIME OF FAILURE, MINUTES
-50	1238.12	0.00	5211.	1733.	0.00	44.25	0.00
-80	1239.60	0.00	5854.	3115.	0.00	44.00	0.00
.90	1240.06	0.00	6059.	3587.	0.00	44.00	0.00
.90	1240.31	0.00	6264.	4059.	0.00	43.75	0.00
	ELEVATION	INITIAL VALUE	SPILLWAY CHEST	TOP OF DAM			
	STORAGE	1234.99	1235.00	1241.00			
	OUTFLOW	3940.	3943.	6500.			
		0.	0.	4620.			

LIST OF REFERENCES

1. "Recommended Guidelines for Safety Inspection of Dams," prepared by Department of the Army, Office of the Chief of Engineers, Washington, D. C. (Appendix D).
2. "Unit Hydrograph Concepts and Calculations," by Corps of Engineers, Baltimore District (L-519).
3. "Seasonal Variation of Probable Maximum Precipitation East of the 105th Meridian for Areas from 10 to 1,000 Square Miles and Duration of 6, 12, 24, and 48 Hours," Hydrometeorological Report No. 33, prepared by J. T. Riedel, J. F. Appleby and R. W. Schloemer, Hydrologic Service Division Hydrometeorological Section, U. S. Department of the Army, Corps of Engineers, Washington, D. C., April 1956.
4. Design of Small Dams, U. S. Department of the Interior, Bureau of Reclamation, Washington, D. C., 1973.
5. Handbook of Hydraulic, H. W. King and E. F. Brater, McGraw-Hill, Inc., New York, 1963.
6. Standard Handbook for Civil Engineers, F. S. Merritt, McGraw-Hill, Inc., New York, 1968.
7. Open-Channel Hydraulics, V. T. Chow, McGraw-Hill, Inc., New York, 1959.
8. Weir Experiments, Coefficients, and Formulas, R. E. Horton, Water Supply and Irrigation Paper No. 200, Department of the Interior, United States Geological Survey, Washington, D. C., 1907.
9. "Probable Maximum Precipitation Susquehanna River Drainage Above Harrisburg, Pennsylvania," Hydrometeorological Report 40, prepared by H. V. Goodyear and J. T. Riedel, Hydrometeorological Branch Office of Hydrology, U. S. Weather Bureau, U. S. Department of Commerce, Washington, D. C., May 1965.
10. Flood Hydrograph Package (HEC-1) Dam Safety Version, Hydrologic Engineering Center, U. S. Army, Corps of Engineers, Davis, California, July 1978.
11. "Simulation of Flow Through Broad Crest Navigation Dams with Radial Gates," R. W. Schmitt, U. S. Army, Corps of Engineers, Pittsburgh District.

12. "Hydraulics of Bridge Waterways," BPR, 1970, Discharge Coefficient Based on Criteria for Embankment Shaped Weirs, Figure 24, page 46.
13. Applied Hydraulics in Engineering, Morris, Henry M. and Wiggert, James N., Virginia Polytechnic Institute and State University, 2nd Edition, The Ronald Press Company, New York, 1972.
14. Standard Mathematical Tables, 21st Edition, The Chemical Rubber Company, 1973, page 15.
15. Engineering Field Manual, U. S. Department of Agriculture, Soil Conservation Service, 2nd Edition, Washington, D. C. 1969.
16. Water Resources Engineering, R. K. Linsley and J. B. Franzini, McGraw-Hill, Inc., New York, 1972.
17. Engineering for Dams, Volume 2, W. P. Creager, J. D. Justin, J. Hinds, John Wiley & Sons, Inc., New York, 1964.

APPENDIX E

FIGURES

LIST OF FIGURES

<u>Figure</u>	<u>Description/Title</u>
1	Regional Vicinity and Watershed Boundary Map
2	Topography and Location Map
3	Embankment Plan
4	Profile of Core Borings
5	Embankment Sections
6	Spillway Plan and Details
7	Spillway Sections
8	Spillway and Outlet Channel Section
9	Steel Reinforcement
10	Outlet Works

FIGURE 1

REGIONAL VICINITY
AND
WATERSHED BOUNDARY MAP

WATERSHED BOUNDARY

LONGEST WATERCOURSE
CENTROID OF DRAINAGE AREA

TROUT RUN, PA.

N4122 5—W7700/7 5

1965

PHOTOREVISED 1973

G A M B L E

ROSE VALLEY LAKE DAM



COGAN STATION, PA.

N4115—W7700/7 5

1965


PHOTOREVISED 1973

BODINES, PA.


NW/4 WARRENSVILLE 15' QUADRANGLE
N4122 5—W7652 5/7 5

1965

PHOTOREVISED 1973





NOTE
FROM C OF EMBANKMENT TO CENTER
OF BORROW AREA APPROX 550'





EMBANKMENT PLAN
SCALE: 1" = 30'



LEGEND
SEALED
SEAL






NOTE
ALL DIMENSIONS AND MEASUREMENTS SHALL BE CHECKED
AND VERIFIED BY THE CONTRACTOR AT THE SITE


<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> SEAL  </div> <div style="text-align: center;"> SEAL  </div> </div>		REVISED 	APPROVALS APPROVED: <i>[Signature]</i> DIRECTOR, BUREAU OF HIGHWAYS & TRANSPORTATION PENNSYLVANIA DEPARTMENT OF TRANSPORTATION HARRISBURG, PENNSYLVANIA DATE: 10-17-70	PROJECT NO. FC-195L (93915-1) EMBANKMENT PLAN MILL CREEK DAM SITE SAMPLE TOWNSHIP, LYCOMING COUNTY PENNSYLVANIA ROY R. FRANK — REGISTERED ENGINEER R. E. T. JERRY SHORE, PENNA.
		<div style="display: flex; justify-content: space-between;"> <div style="width: 45%;"> DESIGNED BY DATE CHECKED BY DATE GMB 10-15-70 KEM 10-17-70 </div> <div style="width: 50%;"> COMMONWEALTH OF PENNSYLVANIA ROY R. FRANK — REGISTERED ENGINEER PENNSYLVANIA PERM. NO. 10177 ROBERT J. BIELLO — ERIC DIRECTOR HARRISBURG, PENNSYLVANIA </div> </div>		




PROFILE 'X-X' @ CONDUIT STA 2+38
PERPENDICULAR TO EMBANKMENT 1




FOREBAY AREA
PERPENDICULAR TO EMBANKMENT 1



END OF WEIR
PERPENDICULAR TO EMBANKMENT 1






PROFILE OF SPILLWAY & LOCATION
OF DRY BRANCHMENT 2

LEGEND

NOTE: ALL DATA SHOWN ABOVE HAS BEEN OBTAINED BY THE ENGINEER FOR THEIR OWN USE IN DESIGNING THIS PROJECT. IT'S ACCURACY OR COMPLETENESS IS NOT GUARANTEED. SEE SPECIAL REQUIREMENTS.


<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>SEAL</p> </div> <div style="text-align: center;"> <p>SEAL</p> </div> </div>		<p>REVISED</p> <table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>								<p>APPROVALS</p> <p><i>Roy R. Frank</i> PROJECT ENGINEER ROY R. FRANK, REGISTERED ENGINEER NO. 1, JERSEY SHORE, PENNSA.</p>	<p>PROJECT NO. FC-195L (93915-1)</p> <p>PROFILE OF CORE BORINGS</p> <p>MILL CREEK DAM SITE DANIEL TOWNSHIP, LYCOMING COUNTY PENNSYLVANIA</p> <p>ROY R. FRANK — REGISTERED ENGINEER NO. 1, JERSEY SHORE, PENNSA.</p> <p>CONSULTANTS OF PENNSYLVANIA WILSON J. SHARP — OWNER PENNSYLVANIA FOR CONSTRUCTION ROY R. FRANK — CIVIL ENGINEER PENNSYLVANIA — PENNSYLVANIA</p> <p>FILED NO. FC-195L-195L PAGE 4 OF 27</p>




NOTES


1. ALL SELECTED IMPROVED FILL SHALL BE SELECTED IMPROVED AND STRATIFIED SOIL MATERIAL FREE FROM DEBRIS AND SHALL BE PLACED IN LAYERS NOT THICKER THAN 24 INCHES IN MAXIMUM COMPRESSION.
2. ALL SELECTED FILL SHALL BE SELECTED SOIL IMPROVED AND STRATIFIED SOIL MATERIAL FREE FROM DEBRIS AND SHALL BE PLACED IN LAYERS NOT THICKER THAN 24 INCHES IN MAXIMUM COMPRESSION.
3. ALL SELECTED FILL SHALL BE SELECTED SOIL IMPROVED AND STRATIFIED SOIL MATERIAL FREE FROM DEBRIS AND SHALL BE PLACED IN LAYERS NOT THICKER THAN 24 INCHES IN MAXIMUM COMPRESSION.
4. ALL SELECTED FILL SHALL BE SELECTED SOIL IMPROVED AND STRATIFIED SOIL MATERIAL FREE FROM DEBRIS AND SHALL BE PLACED IN LAYERS NOT THICKER THAN 24 INCHES IN MAXIMUM COMPRESSION.
5. DRAINAGE DITCHES FOR TYPE AND LOCATION SEE DETAILS AND WRITTEN SPECIFICATIONS.
6. EMBANKMENT CONSTRUCTION DETAILS SEE WRITTEN SPECIFICATIONS AND DRAINAGE DITCHES.
7. ALL DIMENSIONS AND MEASUREMENTS SHALL BE CHECKED AND VERIFIED BY THE CONTRACTOR AT THE SITE.
8. DIMENSIONS SHOWN FOR CUT OFF TRENCH ARE MINIMUM. FINAL DEPTH SHALL BE DETERMINED DURING EXCAVATION BY THE CONTRACTOR.

DETAIL FOR DRAIN INSTALLATION
SCALE 1"=4'-0"



SEAL		SEAL		REVISED	APPROVALS	PROJECT NO. FC-195L (93915-1)
[Seal]		[Seal]			EMBANKMENT SECTIONS MILL CREEK DAM SITE GABLE TOWNSHIP, LYONING COUNTY PENNSYLVANIA ROY S. FRANK - ASSISTANT ENGINEER R.S. 1, JERSEY SHORE, PENNA.	SCALE: 1"=4'-0" SHEET NO. 5 OF 27
[Seal]		[Seal]			ENGINEER OF PENNSYLVANIA ROY S. FRANK PENNSYLVANIA ROY S. FRANK - ASSISTANT ENGINEER R.S. 1, JERSEY SHORE, PENNA.	SCALE: 1"=4'-0" SHEET NO. 5 OF 27







CROSS SECTION @ STATION 0+40




CROSS SECTION @ STATION 0+60



CROSS SECTION @ STATION 0+75



CROSS SECTION @ STATION 1+00




CROSS SECTION @ STATION 1+25

CROSS SECTION @ STATION 1+50


CROSS SECTION @ STATION 1+75

NOTE
ALL DIMENSIONS AND MEASUREMENTS SHALL BE CHECKED
AND VERIFIED BY THE CONTRACTOR AT THE SITE.


SEAL		SEAL		REVISED		APPROVALS		PROJECT NO. F.C.-195L (93915-1)	
						SUBMITTED BY: <i>[Signature]</i> CHECKED BY: <i>[Signature]</i> DATE: <i>[Date]</i>		SPILLWAY SECTIONS MILL CREEK DAM SITE SAMBLE TOWNSHIP, LYCOMING COUNTY PENNSYLVANIA ROY R. FRANK — REGISTERED ENGINEER R.E.T., JERSEY SHORE, PENNA.	
						DESIGNED BY: <i>[Signature]</i> DATE: <i>[Date]</i>		SCALE 1" = 10' H SHEET NO. 7 OF 27	
						CHECKED BY: <i>[Signature]</i> DATE: <i>[Date]</i>		CONFIRMED BY: <i>[Signature]</i> DATE: <i>[Date]</i>	
						DRAWN BY: <i>[Signature]</i> DATE: <i>[Date]</i>		ROBERT A. BILLO — EXEC. DIRECTOR HARRISBURG, PENNSYLVANIA	




CROSS SECTION @ STATION 2+00




CROSS SECTION @ STATION 2+25




CROSS SECTION @ STATION 2+50




CROSS SECTION @ STATION 2+75





NOTE:
ALL DIMENSIONS AND MEASUREMENTS SHALL BE CHECKED
AND VERIFIED BY THE CONTRACTOR AT THE SITE

<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> SEAL ROY R. FRANK </div> <div style="text-align: center;"> SEAL ROY R. FRANK </div> </div>		REVISED 	APPROVALS <i>Roy R. Frank</i> ENGINEER, REGISTERED PROFESSIONAL ENGINEER SUBMITTED BY: <i>Roy R. Frank</i> CHECKED BY: <i>Roy R. Frank</i> DATE: <i>10-25-70</i>	PROJECT NO. FC-195L(93915-1) SPILLWAY & OUTLET CHANNEL SECT. MILL CREEK DAM SITE SAMBLE TOWNSHIP, LYCOMING COUNTY PENNSYLVANIA ROY R. FRANK — REGISTERED ENGINEER R.O.E., JERSEY SHORE, PENNA. SCALE: 1" = 10' HORIZ. 1" = 10' VERT. SHEET NO. FC-195L-52C SHEET 8 OF 27
--	--	--	--	---




1. REINFORCEMENT SHALL BE 5 SECTION 4
2. CRYSTALIZED BARS
3. STEEL WIRE REINFORCEMENT
4. CONCRETE BARS IN
5. STRESS BARS IN
6. THE AMOUNT OF
7. CEMENTS NOT IN
8. ALL BARS WERE
9. ALL REINFORCEMENT
10. ALL REINFORCEMENT
11. ALL REINFORCEMENT
12. REINFORCEMENT
13. REINFORCEMENT
14. REINFORCEMENT
15. REINFORCEMENT
16. REINFORCEMENT
17. REINFORCEMENT
18. REINFORCEMENT
19. REINFORCEMENT
20. REINFORCEMENT
21. REINFORCEMENT
22. REINFORCEMENT
23. REINFORCEMENT
24. REINFORCEMENT
25. REINFORCEMENT
26. REINFORCEMENT
27. REINFORCEMENT
28. REINFORCEMENT
29. REINFORCEMENT
30. REINFORCEMENT
31. REINFORCEMENT
32. REINFORCEMENT
33. REINFORCEMENT
34. REINFORCEMENT
35. REINFORCEMENT
36. REINFORCEMENT
37. REINFORCEMENT
38. REINFORCEMENT
39. REINFORCEMENT
40. REINFORCEMENT
41. REINFORCEMENT
42. REINFORCEMENT
43. REINFORCEMENT
44. REINFORCEMENT
45. REINFORCEMENT
46. REINFORCEMENT
47. REINFORCEMENT
48. REINFORCEMENT
49. REINFORCEMENT
50. REINFORCEMENT
51. REINFORCEMENT
52. REINFORCEMENT
53. REINFORCEMENT
54. REINFORCEMENT
55. REINFORCEMENT
56. REINFORCEMENT
57. REINFORCEMENT
58. REINFORCEMENT
59. REINFORCEMENT
60. REINFORCEMENT
61. REINFORCEMENT
62. REINFORCEMENT
63. REINFORCEMENT
64. REINFORCEMENT
65. REINFORCEMENT
66. REINFORCEMENT
67. REINFORCEMENT
68. REINFORCEMENT
69. REINFORCEMENT
70. REINFORCEMENT
71. REINFORCEMENT
72. REINFORCEMENT
73. REINFORCEMENT
74. REINFORCEMENT
75. REINFORCEMENT
76. REINFORCEMENT
77. REINFORCEMENT
78. REINFORCEMENT
79. REINFORCEMENT
80. REINFORCEMENT
81. REINFORCEMENT
82. REINFORCEMENT
83. REINFORCEMENT
84. REINFORCEMENT
85. REINFORCEMENT
86. REINFORCEMENT
87. REINFORCEMENT
88. REINFORCEMENT
89. REINFORCEMENT
90. REINFORCEMENT
91. REINFORCEMENT
92. REINFORCEMENT
93. REINFORCEMENT
94. REINFORCEMENT
95. REINFORCEMENT
96. REINFORCEMENT
97. REINFORCEMENT
98. REINFORCEMENT
99. REINFORCEMENT
100. REINFORCEMENT

TYPICAL SECTION
SCALE 1/2"=1'-0"
RIGHT SIDE SHOWN
LEFT SIDE OPPOSITE

VERTICAL STEEL IN BACK OF WALL MAY BE
B-W ALTERNATE
B-W ALTERNATE
O-T ALTERNATE

ELEVATION
SCALE 1/2"=1'-0"



SECTION THRU WEIR
SCALE 1/2"=1'-0"

OFFSET JOINT DETAIL
SPILLWAY CHANNEL
SCALE 3/4"=1'-0"

REINFORCEMENT	
M	N
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

CONCRETE WALL OUTLINE
ONE SIDE BATTERED

M	N
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

CONCRETE WALL OUTLINE
BOTH SIDES BATTERED

M	N
1	1
2	2
3	3
4	4
5	5
6	6
7	7
8	8
9	9
10	10
11	11
12	12
13	13
14	14
15	15
16	16
17	17
18	18
19	19
20	20
21	21
22	22
23	23
24	24
25	25
26	26
27	27
28	28
29	29
30	30
31	31
32	32
33	33
34	34
35	35
36	36
37	37
38	38
39	39
40	40
41	41
42	42
43	43
44	44
45	45
46	46
47	47
48	48
49	49
50	50
51	51
52	52
53	53
54	54
55	55
56	56
57	57
58	58
59	59
60	60
61	61
62	62
63	63
64	64
65	65
66	66
67	67
68	68
69	69
70	70
71	71
72	72
73	73
74	74
75	75
76	76
77	77
78	78
79	79
80	80
81	81
82	82
83	83
84	84
85	85
86	86
87	87
88	88
89	89
90	90
91	91
92	92
93	93
94	94
95	95
96	96
97	97
98	98
99	99
100	100

SEAL	SEAL

NOTES


1. REINFORCEMENT SHALL BE INSTALLED AT ALL LOCATIONS AS SHOWN ON THIS DRAWING AND SHALL BE CONFORMANT WITH THE LATEST EDITION OF THE AISC STEEL CONSTRUCTION MANUAL.
2. ALL REINFORCEMENT SHALL BE SPACED AT 12" ON CENTER.
3. STEEL SHALL BE A36 STEEL.
4. CONCRETE SHALL BE 2800 PSI.
5. STEEL SHALL BE ALREADY GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
6. WHERE GALVANIZED STEEL IS USED, IT SHALL BE GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
7. THE GALVANIZED STEEL SHALL BE GALVANIZED THROUGHOUT THE ENTIRE WALLS AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
8. ALL REINFORCEMENT SHALL BE GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
9. ALL REINFORCEMENT SHALL BE GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
10. ALL REINFORCEMENT SHALL BE GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
11. ALL REINFORCEMENT SHALL BE GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
12. ALL REINFORCEMENT SHALL BE GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.
13. ALL REINFORCEMENT SHALL BE GALVANIZED TO THE SURFACE OF THE WALLS TO WEAR AND SHALL HAVE THE 1/8" MINIMUM THICKNESS OF THE GALVANIZED STEEL TO THE SURFACE.


ELEVATION
SCALE 1/2"=1'-0"

REINFORCEMENT CANTILEVERED RETAINING WALLS												HIGHWAY SURCHARGE											
M	N	O	P	Q	R	S	T	U	V	W	X	Y	Z	AA	AB	AC	AD	AE	AF	AG	AH	AI	AJ
1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24
25	26	27	28	29	30	31	32	33	34	35	36	37	38	39	40	41	42	43	44	45	46	47	48
49	50	51	52	53	54	55	56	57	58	59	60	61	62	63	64	65	66	67	68	69	70	71	72
73	74	75	76	77	78	79	80	81	82	83	84	85	86	87	88	89	90	91	92	93	94	95	96
97	98	99	100	101	102	103	104	105	106	107	108	109	110	111	112	113	114	115	116	117	118	119	120

CONCRETE WALL OUTLINE ONE SIDE BATTERED			
1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16
17	18	19	20
21	22	23	24
25	26	27	28
29	30	31	32
33	34	35	36
37	38	39	40
41	42	43	44
45	46	47	48
49	50	51	52
53	54	55	56
57	58	59	60
61	62	63	64
65	66	67	68
69	70	71	72
73	74	75	76
77	78	79	80
81	82	83	84
85	86	87	88
89	90	91	92
93	94	95	96
97	98	99	100
101	102	103	104
105	106	107	108
109	110	111	112
113	114	115	116
117	118	119	120
121	122	123	124
125	126	127	128
129	130	131	132
133	134	135	136
137	138	139	140
141	142	143	144
145	146	147	148
149	150	151	152
153	154	155	156
157	158	159	160
161	162	163	164
165	166	167	168
169	170	171	172
173	174	175	176
177	178	179	180
181	182	183	184
185	186	187	188
189	190	191	192
193	194	195	196
197	198	199	200
201	202	203	204
205	206	207	208
209	210	211	212
213	214	215	216
217	218	219	220
221	222	223	224
225	226	227	228
229	230	231	232
233	234	235	236
237	238	239	240
241	242	243	244
245	246	247	248
249	250	251	252
253	254	255	256
257	258	259	260
261	262	263	264
265	266	267	268
269	270	271	272
273	274	275	276
277	278	279	280
281	282	283	284
285	286	287	288
289	290	291	292
293	294	295	296
297	298	299	300
301	302	303	304
305	306	307	308
309	310	311	312
313	314	315	316
317	318	319	320
321	322	323	324
325	326	327	328
329	330	331	332
333	334	335	336
337	338	339	340
341	342	343	344
345	346	347	348
349	350	351	352
353	354	355	356
357	358	359	360
361	362	363	364
365	366	367	368
369	370	371	372
373	374	375	376
377	378	379	380
381	382	383	384
385	386	387	388
389	390	391	392
393	394	395	396
397	398	399	400
401	402	403	404
405	406	407	408
409	410	411	412
413	414	415	416
417	418	419	420
421	422	423	424
425	426	427	428
429	430	431	432
433	434	435	436
437	438	439	440
441	442	443	444
445	446	447	448
449	450	451	452
453	454	455	456
457	458	459	460
461	462	463	464
465	466	467	468
469	470	471	472
473	474	475	476
477	478	479	480
481	482	483	484
485	486	487	488
489	490	491	492
493	494	495	496
497	498	499	500
501	502	503	504
505	506	507	508
509	510	511	512
513	514	515	516
517	518	519	520
521	522	523	524
525	526	527	528
529	530	531	532
533	534	535	536
537	538	539	540
541	542	543	544
545	546	547	548
549	550	551	552
553	554	555	556
557	558	559	560
561	562	563	564
565	566	567	568
569	570	571	572
573	574	575	576
577	578	579	580
581	582	583	584
585	586	587	588
589	590	591	592
593	594	595	596
597	598	599	600
601	602	603	604
605	606	607	608
609	610	611	612
613	614	615	616
617	618	619	620
621	622	623	624
625	626	627	628
629	630	631	632
633	634	635	636
637	638	639	640
641	642	643	644
645	646	647	648
649	650	651	652
653	654	655	656
657	658	659	660
661	662	663	664
665	666	667	668
669	670	671	672
673	674	675	676
677	678	679	680
681	682	683	684
685	686	687	688
689	690	691	692
693	694	695	696
697	698	699	700
701	702	703	704
705	706	707	708
709	710	711	712
713	714	715	716
717	718	719	720
721	722	723	724
725	726	727	728
729	730	731	732
733	734	735	736
737	738	739	740
741	742	743	744
745	746	747	748
749	750	751	752
753	754	755	756
757	758	759	760
761	762	763	764
765	766	767	768
769	770	771	772
773	774	775	776
777	778	779	780
781	782	783	784
785	786	787	788
789	790	791	792
793	794	795	796
797	798	799	800
801	802	803	804
805	806	807	808
809	810	811	812
813	814	815	816
817	818	819	820
821	822	823	824
825	826	827	828
829	830	831	832
833	834	835	836
837	838	839	840
841	842	843	844
845	846	847	848
849	850	851	852
853	854	855	856
857	858	859	860
861	862	863	864
865	866	867	868
869	870	871	872
873	874	875	876
877	878	879	880
881	882	883	884
885	886	887	888
889	890	891	892
893	894	895	896
897	898	899	900
901	902	903	904
905	906	907	908
909	910	911	912
913	914	915	916
917	918	919	920
921	922	923	924
925	926	927	928
929	930	931	932
933	934	935	936
937	938	939	940
941	942	943	944
945	946	947	948
949	950	951	952
953	954	955	956
957	958	959	960
961	962	963	964
965	966	967	968
969	970	971	972
973	974	975	976
977	978	979	980
981	982	983	984
985	986	987	988
989	990	991	992
993	994	995	996
997	998	999	1000


CONCRETE WALL OUTLINE BOTH SIDES BATTERED			
1	2	3	4
5	6	7	8
9	10	11	12
13	14	15	16
17	18	19	20
21	22	23	24
25	26	27	28
29	30	31	32
33	34	35	36
37	38	39	40
41	42	43	44
45	46	47	48
49	50	51	52
53	54	55	56
57	58	59	60
61	62	63	64
65	66	67	68
69	70	71	72
73	74	75	76
77	78	79	80
81	82	83	84
85	86	87	88
89	90	91	92





OUTLET WORKS - ELEVATION
SCALE 1/8" = 1'-0"

NOTE
SEE DETAIL SHEET NO. 2



OUTLET WORKS - PLAN
SCALE 1/8" = 1'-0"

BE CHECKED
ON SITE

<div style="display: flex; justify-content: space-around;"> <div style="text-align: center;"> <p>SEAL</p> </div> <div style="text-align: center;"> <p>SEAL</p> </div> </div>		<p>REVISED</p> <table border="1"> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> <tr><td> </td></tr> </table>									<p>APPROVALS</p> <p>APPROVED: <i>[Signature]</i> EXEC. DIRECTOR PENNSYLVANIA FISH COMMISSION</p> <p>APPROVAL: <i>[Signature]</i> DIRECTOR, BUREAU OF FISHERIES & ENGINEERING</p> <p>DESIGNED BY: <i>[Signature]</i> CIVIL ENGINEER</p> <p>ACCEPTED BY: <i>[Signature]</i> CONTRACTOR</p> <p>DATE: 12-8-70 CHECKED BY: R.E.H. DATE: 12-23-70</p>	<p>PROJECT NO. F.C.-195L (93915-1)</p> <p>OUTLET WORKS</p> <p>MILL CREEK DAM SITE</p> <p>SAMBLE TOWNSHIP, LYCOMING COUNTY PENNSYLVANIA</p> <p>ROY R. FRANK — REGISTERED ENGINEER R.E.F., JERSEY SHORE, PENNA.</p> <p>COMMONWEALTH OF PENNSYLVANIA ROY R. FRANK — GOVERNOR PENNSYLVANIA FISH COMMISSION ROBERT J. BELLO — EXEC. DIRECTOR HARRISBURG, PENNSYLVANIA</p> <p>SCALE 1/8" = 1'-0" & NOTED</p> <p>NO. FC-195L-32C</p> <p>SHEET NO. 11 OF 27</p>

APPENDIX F

GEOLOGY

Geology

Rose Valley Lake Dam is located within the glaciated portion of the Allegheny High Plateaus section of the Appalachian Plateaus physiographic province of north central Lycoming County, Pennsylvania. The principal bedrock unit present at the dam site is the Catskill member of the Susquehanna Group of Devonian age. Soils, generally on the north, northeast and south shores are derived from glacial till whereas the soils underlying the site of the present reservoir consist of glacial lake sediments. The glacial deposits in the area were developed during Wisconsin time--the most recent period of continental glaciation.

The Catskill member is poorly represented in outcrop throughout the area; however, outcrops in the Mill Creek gorge just west of the dam suggests the Catskill strata in the dam site area is a sequence of red, moderately well-indurated, very fine to fine grained sandstones alternating with moderately well-indurated red shales. The dominance of silt and clay in the soil indicates that shale is the dominant lithology. Weathering of this rock produces a mass of sand, silt and clay with numerous slabs of angular sandstone. This weathered material mantles the unglaciated part of this area and is well developed in the middle reaches of Mill Creek gorge just downstream of the dam.

The glacial till in the area is terminal moraine deposited by a Wisconsin ice advance which came from the northeast.

The glacial till is a red, unsorted, unconsolidated mixture of sand, silt, clay, pebbles, and cobbles with some small boulders. The cobbles are angular plates of red siltstone or sandstone and subangular to well-rounded gray sandstones. The cobbles range in size from three inches to one foot in diameter and the boulders rarely exceed two feet in diameter. The material is almost entirely locally derived from rocks of the Catskill Group and greatly resembles the weathered Catskill material. The clayey nature of the till makes the unit a relatively impermeable mass.


The thickness of the till is not known, but it appears to vary considerably. Some exposures near the tops of hills east of the reservoir show less than 1-foot of till on the Catskill Group rocks while the morphology of some of the area suggests that the till may be 50 feet or more thick along the southeastern margin of the reservoir.

The reservoir area is floored by a light-gray, somewhat iron-stained, relatively impermeable, silty clay lake deposit which is at least four feet thick. The clay is probably

thickest in the eastern part of the reservoir area and the margins of the deposit probably contain intermixed sand and gravel.

Structurally, the site lies nearly on the axial trace of the Rose Valley anticline. The Rose Valley anticline is a doubly plunging structure of low relief trending in an east-northeast and west-southwest direction. At the dam site, the bedrock surface dips gently to the southwest.

- ¹Denny, Charles S and Lyford, Walter H., "Surficial Geology and Soils of the Elmira-Williamsport Region, New York and Pennsylvania," Geological Survey Professional Paper 379, United States Government Printing Office, Washington, D. C., 1963.
- ²Lohman, Stanley W., "Ground Water in Northcentral Pennsylvania," Pennsylvania Geological Survey Fourth Series, Bulletin 26, Harrisburg, Pennsylvania, 1939.
- ³Sevon, William D., "Geology of the Proposed Mill Creek Dam Site, Gamble Township, Lycomina County, Pennsylvania," Pennsylvania Geologic Survey, Harrisburg, Pennsylvania, 1966.



LEGEND

PENNSYLVANIAN



Pottsville Group

Light gray to white, coarse grained sandstones and conglomerates with some mineable coal, includes Sharp Mountain, Schuylkill, and Tumbling Run Formations.

MISSISSIPPIAN



Mauch Chunk Formation

Red shales with brown to greenish gray flaggy sandstones, includes Greenbrier Limestone in Fayette, Westmoreland, and Somerset counties, Loganoma Limestone at the base in southeastern Pennsylvania.



Pocono Group

Predominantly gray, hard, massive, cross-bedded conglomerate and sandstone with some shale, includes in the Appalachians Plateau, Harpoon, Shenango, Cuyahoga, Cassinanga, Carry, and Knapp Formations. Includes part of Oswayo of M. L. Fuller in Potter and Tioga counties.

DEVONIAN



Susquehanna Group


barbed line is "Chemung-Catskill" contact of Second Pennsylvania Survey County reports; barbs on "Chemung" side of line.

— Border of Illinoian drift

• • • Border of Wisconsin drift

Note: The bedrock surface is covered with Pleistocene age Wisconsin and Illinoian till composed of sands, gravels and silty clays of variable thicknesses.

Scale



GEOLOGY MAP

REFERENCE

GEOLOGY MAP OF PENNSYLVANIA PREPARED BY COMMONWEALTH OF PENNA. DEPT. OF INTERNAL AFFAIRS, DATED 1960, SCALE 1" = 4 MILES

gai
CONSULTANTS, INC.